

## Project Closeout Meeting

Date: December 17, 1999

Attending: Craig Marvick

Phil Mescher

Ralph

Stu Turner

Dr Reg Souleyrette

Richard Storm

Jerry Shadewald

Stu -- Have had some "run-time" errors with VB.

*Probably has more to do with file structure*

Reg -- Will recommend some changes in the terminology.

May be able to convert CE 451 labs into a tutorial.

Phil -- Were not able to obtain a "test license" of MM2K; therefore, tried to purchase a copy. VHB had troubles integrating turn prohibitors; return the software without ever loading it.

Suggestions --

- Change some of the wording on the "Default Model Builder".
- Make sure that the "Join a Model Run" is updated.
- Add restrictions that may be applied by Tranplan. Such as that Stochastic model does not support select link analysis or shortest path creation.
- Allow user to choose impedance for the shortest path.
- Add a "CANCEL" button on the "Clear Records" form of the OD Desire Line Visual Basic program.
- Remove centroid connectors in the screen/cut line reports.
- Look into the L/C ratio in the screen/cut lines
- Rename the Visualization and Calibration plots to Calibration and Validation respectively.
- Ask user for the number of dummy zones when building a network in ArcView.